MATERIAL SAFETY DATA SHEET

LaMOTTE COMPANY
PO BOX 329 - CHESTERTOWN - MARYLAND - 21620
TELEPHONE # FOR INFORMATION 410-778-3100

24 Hour Emergency Number (CHEM-TEL) 800-255-3924

1. PRODUCT IDENTIFICATION

Free Chlorine UDV; DPD 1B Free Chlorine Reagent *Code Nr.* **6741**

2. HAZARDOUS INGREDIENTS

NAME	*CAS #*	*TSCA #*	*%*	*PEL*	*TLV*
N, N-Diethyl-1, 4-phenylene-diamine sulfate	6283-63-2	6065-27-6	<1	N/E	N/E
Phosphorous Acid	13598-36-2		<2	N/E	N/E
All other ingredients are proprietary NJTSRN 80100291-5046p					

3. NON-HAZARDOUS INGREDIENTS EXCEPT WATER (7732-18-5)

NAME	*CAS #*	*%*
All other ingredients are proprietary NJTSRN 80100291-5046p		

4. PHYSICAL DATA

Appearance: Clear Colorless Liquid

Solubility in Water: Soluble	*Odor:* None	*Boiling Point:* Unknown	*Melt. Point:* N/A
Vapor Pressure: Unknown	*Vapor Density:* Unknown	*pH:* 2	

5. FIRE AND EXPLOSION DATA

Flash Point (method used) N/A | *Flammable Limit: LEL:* N/A | *UEL:* N/A

Extinguishing Media: Not a fire hazard

HMIS Hazard: Health - 1 *Flammability -* 0 *Reactivity -* 0 *Scale: 4 = Extreme, 3 = High, 2 = Moderate, 1 = Slight, 0 = Least*

Special Fire Fighting Procedures:
N/A

Unusual Fire & Explosion Hazard:
N/A

6. REACTIVITY DATA

Stability:
☒ *Stable*
☐ *Unstable*

Conditions to avoid: Heat, light

Incompatibility (Materials to avoid):
N/A

Hazardous Decomposition Products: N/A

7. HEALTH HAZARD DATA

Toxicity: Unknown

Primary Route of Entry: ☐ *Inhalation* ☒ *Skin* ☒ *Ingestion* ☐ *N/A*

Carcinogenicity: ☒ *None* ☐ *NTP* ☐ *OSHA* ☐ *IARC*

Other Health Related Comments:

Target Organs: N/A

Signs and symptoms of exposure:
May irritate eyes and skin. Harmful if swallowed.

Medical Condition Aggravated by Exposure: N/A

8. EMERGENCY FIRST AID PROCEDURES

Eye Contact: Flush thoroughly with water for 15 minutes. Consult a physician.

Ingestion: Rinse out mouth. Drink 1-2 glasses of water. Consult physician.

Inhalation:
N/A

Skin Contact:
Flush with water. Remove affected clothing and wash skin with soap and water.

9. SPILL AND DISPOSAL PROCEDURES

Spill and Leak:
Cover spill with sodium bicarbonate. Scoop up slurry and wash down drain with excess water.

Disposal:
Add slowly to a solution of sodium carbonate and calcium hydroxide. Pour neutralized solution down drain with excess water. Dispose according to federal, state and local regulations.

10. PRECAUTIONARY MEASURES

In Handling: ☒ *Gloves* ☒ *Eye Protection* ☐ *N/A* ☒ *Other:* Lab Coat

Ventilation ☒ *Normal* ☐ *Mechanical* ☐ *Respiratory Protection*

Work/Hygienic Practices: Avoid contact with skin and clothing.

11. SPECIAL PRECAUTIONS

Store away from heat and light.

DATE: 10/18/01

The above information is believed to be correct but does not claim to be all inclusive and should be used only as a guide.

^ This is a toxic chemical subject to reporting requirements of section 313 of EPCRA and 40CFR372.